


Preliminary Steps:

1. Read all instructions carefully and study diagrams before installing the work light
2. Check with state and local authorities for laws governing usage and proper mounting
3. Disconnect ground connection from battery (marked "-") to avoid accidental short circuits before attempting to connect electrical wires
4. Route new wires along existing wiring. Tape as necessary to correct slack
5. When running wires through the firewall, keep them away from moving parts

Mounting and installation:

1. Drill 8.5 mm holes for screw placement on the surface where you would like to fix the light
2. Use the bolt to fasten the light, add the locking washer and tighten the bolt
3. Cable colors:
Red: Power (+)
Black: Ground (-)

Hydra30



Warning!

1. Works under the specified voltage (DC9-36V)
2. This light becomes hot under continuous use. Don't remove or touch the casing for at least 30 minutes after turning the light off
3. Keep heat-sink clean and exposed to maintain air flow